

From: [Coltrain, Katrina](#)
To: [McMillan, Teresa](#)
Cc: todd.downham@deq.ok.gov; lvega_eaest.com
Subject: RE: Wilcox TO 128 - HSP
Date: Tuesday, December 08, 2015 1:43:00 PM
Attachments: [1956 process-tank areas.pdf](#)
[Pipeline contact information.jpg](#)

Teri, please find a few comments listed below for your consideration.

- 1.2.1: In the second paragraph it is stated that 19 people live onsite (Approximately 19 people live onsite and over 5,000 people live within 2 miles.) There have been changes regarding the homes and 19 is no longer a good representation of the number of people living onsite. Please revise this to indicate that 4 residential properties are currently occupied.
- 1.2.1, bullets describing site area of interest.
 - Please revise the areas to those as presented in the attached Map.
 - The residential property associated with the church, as well as the church, are vacant.
 - The eastern drainage/creek is always full of water. I am not certain that it has been defined appropriately. We will need to verify during RI.
 - The owner of the pipeline is Magellan. Contact information attached.
- Table 2: consider including
 - dogs as many of the residents have pets.
 - I see reflective vests mentioned, but did not see hard hats, boots, and glasses listed.
 - Vapors: there is a potential due to the nature of the waste. Respirators may be necessary.
- 3.1.1:
 - You may want to document that the pipeline is active and can have at any given time kerosene, gasoline, jet fuel, diesel, etc. running through it. Also, the pipeline is not that deep and can be found anywhere between 2 and 4 ft down so the use of heavy equipment around the pipeline or moving over the pipeline should first be reviewed.
 - Resident also have natural gas running to their homes, so care should be taken to identify these lines.
- 3.1.7: During the phase 1, a call was made for the utilities to be marked. Though some were marked, the job was far from complete. The team had a person on site nearly the entire time to screen areas that we were going to be doing any subsurface work. It proved to be effective and beneficial. He marked much of what he found, but whether those markings will remain in the future is unknown.
- It appears that the HSP is duplicated after the title page for Appendix E (pdf page 56) with the ERT figures starting on pdf page 112.

Katrina Higgins-Coltrain
Remedial Project Manager
US EPA Region 6
LA/OK/NM Section (6SF-RL)
1445 Ross Avenue

Dallas, Texas 75202
214-665-8143

From: McMillan, Teresa [mailto:tmcmillan@eaest.com]
Sent: Monday, November 30, 2015 5:22 PM
To: Coltrain, Katrina
Cc: todd.downham@deq.ok.gov; lvega_eaest.com
Subject: Wilcox TO 128 - HSP

Katrina,

Please find the Health and Safety Plan for the Wilcox Oil Company Superfund Site for your review. Would you like the word copy of the document sent to you on a compact disc or would you prefer that I email it to you.

Also, would you like me to submit the Health and Safety Plan to the trustee's or will you be doing so?

Thanks,

Teri McMillan, PG
EA Engineering, Science, and Technology, Inc., PBC
320 Gold Ave SW, Suite 1300
Albuquerque, New Mexico 87102
(505) 715-4332